


komponenty pro dvě křídla



x4

L-050



x4

4411





x4


4422




FAST S s horní a spodní lištou L-050




10-42 mm	Počet křídel	n = 2	n = 3	n = 4	n = 5	n = 6	n = 7	n = 8
	Výška křídla [mm]	$hP = H - 12$						
	Šířka křídla [mm]	$bP = (S + 40) / 2$	$bP = (S + 80) / 3$	$bP = (S + 120) / 4$	$bP = (S + 160) / 5$	$bP = (S + 200) / 6$	$bP = (S + 240) / 7$	$bP = (S + 280) / 8$




1





2




3



4



5



6

